


# DIECUT PROCESS




DATE: MARCH 2, 2023

Condition of the blade.

\* Used cushion crease

Return the standard usage of  
cushion crease for Louvre SF  
model.



DATE: MARCH 2, 2023

JO: 31681

ITEM CODE: 515913300

ITEM DESCRIPTION: LOUVRE 2 MJX ICB  
FOR CHINA2

PLAN: 315 SETS

REJECT: PANEL A = 8 ; PANEL B 8

REMARKS: DUE TO DELIVERY ERROR AND  
NO BURSTING ENCOUNTERED





DATE: MARCH 2, 2023

JO: 31682

ITEM CODE: 515909300

ITEM DESCRIPTION: LOUVRE 2 MCX ICB  
FOR CHINA CC350

PLAN: 1000 SETS

REJECT: PANEL B = 3

REMARKS: DUE TO MISALIGN CUT AND  
NO BURSTING ENCOUNTERED



DATE: MARCH 2, 2023

JO: 31712

ITEM CODE: 516297800

ITEM DESCRIPTION: LOUVRE 2 MDX ICB  
FOR ASIA WH;C CC350

PLAN: 1 100 SETS

REJECT: 0

REMARKS: NO BURSTING ENCOUNTERED



## SEMI-AUTO GLUING PROCESS



For semi-auto gluing process, operator's feedback was they do not encounter bloated on the creasing line when they folding the item.

## SEMI-AUTO GLUING PROCESS



JO: 31681  
ITEM CODE: 515913300



JO: 31682  
ITEM CODE: 515909300



JO: 31712  
ITEM CODE: 516297800

