



KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 5457-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

Control No.:

Date Issued


0082

250410

Customer	CANON BUSINESS MACHINE PHILS.	Attention To	REXEL ALMARIO
Item Code	6CB-0005-000	Department	PRODUCTION
Item Description	BODY	Date of Detection	250404
Job Order Number	JO-F-25-344-10	Section Detected	QA SCREENING

ILLUSTRATION OF THE PROBLEM

ACTUAL: Heavy scoring
end to end
REQUIREMENT: No
heavy scoring



Lot Quantity (pcs)	Reject Qty (pcs)	Reject %
3000	70	2.33
Nature of Defect:		
HEAVY SCORING		
Requirement:		
No heavy scoring		
Actual		
Heavy scoring end to end		

NO. OF OCCURENCE	DISPOSITION	AREA OF OCCURENCE / ORIGIN	CONTENT
<input type="checkbox"/> First <input checked="" type="checkbox"/> Recurrence No.: <u>2</u> Date.: <u>250403</u>	<input type="checkbox"/> Hold <input type="checkbox"/> Special Acceptance <input type="checkbox"/> For Rework <input checked="" type="checkbox"/> Reject / Disposal	<input type="checkbox"/> Slotter <input type="checkbox"/> EQOS <input type="checkbox"/> Diecut <input type="checkbox"/> Detaching <input checked="" type="checkbox"/> Gluing <input type="checkbox"/> Vertical <input type="checkbox"/> Others	<input type="checkbox"/> Material <input type="checkbox"/> Dimension <input type="checkbox"/> Appearance <input checked="" type="checkbox"/> Process / Method
Issued by	Checked by	Approved by	Received by (Receiving Section)
LESTER JOHN DIOSO 250410	CHARLENE JAN MARIE FLORES 250421	MICHAEL CASILLANO 250422	GERALD DE GUZMAN 250506

I. INVESTIGATION / ANALYSIS

DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)

System / Training

Design / Toolings

Process / Material

WHY 1 : Scoring occurs during staging of item to caster pallet

WHY 2 : The item exceeded in the caster pallet that resulted to the item to bend.

WHY 3 : The size of the item is longer than the caster pallet.

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 5457-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)****System / Training****Design / Toolings****Process / Material**

WHY 1 : na

FINAL CONCLUSION**CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)****WHO / WHEN****Process / Material**

WHY 1: Purchase of plywood to used as protection for bigsheet items to prevent damage and scoring

Production Leader // 2025-05-21

IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)**A. Sorting Result****C. Reworking**

	Location	Total Stock	NG	Total Good	Rework Quantity	na
RM	na	0	0	0	Total Good	na
WIP	na	0	0	0	Rework PPM (Good)	na
FG	na	0	0	0		

B. Orientation

Date	2025-05-15	Time	08:13
Title	na		
Attendees	na		

Prepared By:**Approved By:**

GERALD DE GUZMAN | 250520

N/A

Department Head

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 5457-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)**

Date Conducted:	PIC:
Identified Rootcause	Recommendation

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)

	Checked By:	Date	Implemented?	Running	JO Number	Date	NG Qty	Lot Qty
1st Verification of Action			[] Yes [] No	1st				
2nd Verification of Action			[] Yes [] No	2nd				
3rd Verification of Action			[] Yes [] No	3rd				
Effectiveness of Action			[] Yes [] No	4th				
Remarks:				5th				

IV. CLOSURE

Status	Remarks
Still Open	

Approved by:		Process Owner Acknowledgment: (Receiving Section)	
N/A	N/A	N/A	N/A
QA Head	Top Management	Line Leader	Department Head
Date: -	Date: -	Date: -	Date: -