


**KANE PACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
 Telephone No. (049) 5457-7166 to 69
 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

Control No.:	Date Issued
0027	241113

Customer	SUPERFLEX LOGISTICS, INC	Attention To	MICHAEL CASILLANO
Item Code	AZ409300 LOWER PAD-RMFG	Department	QUALITY ASSURANCE
Item Description	LOWER PAD; A	Date of Detection	241107
Job Order Number	JO-24-IPD-01038-2	Section Detected	QA SCREENING

ILLUSTRATION OF THE PROBLEM

Lot Quantity (pcs)	Reject Qty (pcs)	Reject %
--------------------	------------------	----------

100	65	65.00
-----	----	-------

Nature of Defect:

OVER CUT

Requirement:

Should be creasing line

Actual

Overcut on creasing line

NO. OF OCCURENCE	DISPOSITION	AREA OF OCCURENCE / ORIGIN	CONTENT
<input checked="" type="checkbox"/> First <input type="checkbox"/> Recurrence No.: <u>1</u> Date.: <u>241107</u>	<input type="checkbox"/> Hold <input type="checkbox"/> Special Acceptance <input type="checkbox"/> For Rework <input checked="" type="checkbox"/> Reject / Disposal	<input type="checkbox"/> Slotter <input type="checkbox"/> EQOS <input type="checkbox"/> Diecut <input type="checkbox"/> Detaching	<input type="checkbox"/> Gluing <input type="checkbox"/> Vertical <input checked="" type="checkbox"/> Others <input type="checkbox"/> DIECUT / DETACHING
Issued by	Checked by	Approved by	Received by (Receiving Section)
LESTER JOHN DIOSO 241113	CHARLENE JAN MARIE FLORES 241118	MICHAEL CASILLANO 241118	GERALD DE GUZMAN 241128

I. INVESTIGATION / ANALYSIS**DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)**

System / Training

Design / Toolings

Process / Material



INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)

System / Training

Design / Toolings

Process / Material

FINAL CONCLUSION

CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)

WHO / WHEN

IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)

A. Sorting Result					C. Reworking	
	Location	Total Stock	NG	Total Good	Rework Quantity	
RM					Total Good	
WIP						
FG					Rework PPM (Good)	

B. Orientation

Date		Time	
Title			
Attendees			
Prepared By:		Approved By:	
N/A		N/A	
			Department Head

**KANE PACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISI II, Brgy. La Mesa, Calamba City, Laguna
 Telephone No. (049) 5457-7166 to 69
 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)**

Date Conducted:	PIC:
Identified Rootcause	Recommendation

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)

	Checked By:	Date	Implemented?	Running	JO Number	Date	NG Qty	Lot Qty
1st Verification of Action			<input type="checkbox"/> Yes <input type="checkbox"/> No	1st				
2nd Verification of Action			<input type="checkbox"/> Yes <input type="checkbox"/> No	2nd				
3rd Verification of Action			<input type="checkbox"/> Yes <input type="checkbox"/> No	3rd				
Effectiveness of Action			<input type="checkbox"/> Yes <input type="checkbox"/> No	4th				
Remarks:				5th				

IV. CLOSURE

Status	Remarks		
Still Open			
Approved by:		Process Owner Acknowledgment: (Receiving Section)	
MICHAEL CASILLANO 250507 08:35 QA Head	KOHEI ISHII 250523 02:41 Top Management	GERALD DE GUZMAN 250603 08:41 Line Leader	REXEL ALMARIO 251017 09:41 Department Head
Date: 25252525-05-07	Date: 25252525-05-23	Date: 25252525-06-03	Date: 25252525-10-17