

**KANE PACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
 Telephone No. (049) 5457-7166 to 69
 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

Control No.:	Date Issued
0097	260108

Customer	EPSON PRECISION PHILIPPINES INCORPORATED - IJP	Attention To	WEENA APALLA
Item Code	513671100	Department	KP LIMA PRODUCTION
Item Description	OUTER CARTON BOX	Date of Detection	260107
Job Order Number	JOL-00023241	Section Detected	SA-2600

ILLUSTRATION OF THE PROBLEM

Lot Quantity (pcs)	Reject Qty (pcs)	Reject %
--------------------	------------------	----------

2500	112	4.48
------	-----	------

Nature of Defect:

PEEL OFF

Requirement:

THE ITEM SHOULD BE IN GOOD CONDITION NO OCCURENCE OF PEEL OFF

Actual

THE PEEL OFF OCCUR ON LOWER PORTION B/C

NO. OF OCCURENCE	DISPOSITION	AREA OF OCCURENCE / ORIGIN	CONTENT
<input type="checkbox"/> First	<input type="checkbox"/> Hold	<input type="checkbox"/> Slotter	<input type="checkbox"/> Material
<input checked="" type="checkbox"/> Recurrence No.: <u>0</u>	<input type="checkbox"/> Special Acceptance	<input checked="" type="checkbox"/> EQOS	<input type="checkbox"/> Dimension
Date.: <u>260107</u>	<input type="checkbox"/> For Rework	<input type="checkbox"/> Vertical	<input type="checkbox"/> Appearance
	<input checked="" type="checkbox"/> Reject / Disposal	<input type="checkbox"/> Diecut	<input checked="" type="checkbox"/> Process / Method
		<input type="checkbox"/> Detaching	

Issued by

Checked by

Approved by

Received by (Receiving Section)

JAM NIKKA MACARAIG | 260108

MELFORD ANONUEVO | 260108

RODERICK RAMOS | 260114

Glen Magsino | 260120

I. INVESTIGATION / ANALYSIS**DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)****System / Training****Design / Toolings****Process / Material**

**INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)****System / Training****Design / Toolings****Process / Material****FINAL CONCLUSION****CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)****WHO / WHEN****IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)**

A. Sorting Result					C. Reworking	
	Location	Total Stock	NG	Total Good	Rework Quantity	
RM					Total Good	
WIP						
FG					Rework PPM (Good)	

B. Orientation

Date		Time	
Title			
Attendees			
Prepared By:		Approved By:	
N/A		N/A	
			Department Head

**KANE PACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISI II, Brgy. La Mesa, Calamba City, Laguna
 Telephone No. (049) 5457-7166 to 69
 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)**

Date Conducted:	PIC:
Identified Rootcause	Recommendation

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)

	Checked By:	Date	Implemented?	Running	JO Number	Date	NG Qty	Lot Qty
1st Verification of Action			<input type="checkbox"/> Yes <input type="checkbox"/> No	1st				
2nd Verification of Action			<input type="checkbox"/> Yes <input type="checkbox"/> No	2nd				
3rd Verification of Action			<input type="checkbox"/> Yes <input type="checkbox"/> No	3rd				
Effectiveness of Action			<input type="checkbox"/> Yes <input type="checkbox"/> No	4th				
Remarks:				5th				

IV. CLOSURE

Status	Remarks		
Still Open			
Approved by:		Process Owner Acknowledgment: (Receiving Section)	
N/A QA Head	N/A Top Management	N/A Line Leader	N/A Department Head
Date: -	Date: -	Date: -	Date: -