


INVESTIGATION REPORT FOR PEEL OFF OF 516298200 LOUVRE 2 MCX ASIA

DIRECT CAUSE METHOD (MATERIAL)

W1: Peel off occurred due to splashing.

W2: During running the glue was sprinkled in the glue roller to the splashing cover.

W3: Due to high glue viscosity



PRODUCTION ACTION PLAN

Immediate Action:

> Cleaning of splashing cover for every 500pcs



Prepared by:

PRODUCTION IE

Reviewed by:

Noemi Cepeda
PRODUCTION SUPERVISOR

