



ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF WRONG FLUTE USED

Actual:

WRONG FLUTE COMBINATION ENCOUNTERED ON THE ITEM
(PLEASE SEE ATTACHED PICTURE)

NO. OF OCCURRENCE		DISPOSITION		AREA OF OCCURRENCE / ORIGIN		CONTENT	
<input checked="" type="checkbox"/> First		<input type="checkbox"/> Hold		<input type="checkbox"/> Slotter	<input type="checkbox"/> Gluing	<input type="checkbox"/> Material	
<input type="checkbox"/> Recurrence		<input checked="" type="checkbox"/> Special Acceptance		<input type="checkbox"/> EQOS	<input type="checkbox"/> Vertical	<input type="checkbox"/> Dimension	
No.:		<input type="checkbox"/> For Rework		<input type="checkbox"/> Diecut	<input checked="" type="checkbox"/> Other LUCIDA	<input type="checkbox"/> Appearance	
Date:		<input type="checkbox"/> Reject / Disposal		<input type="checkbox"/> Detaching		<input checked="" type="checkbox"/> Process / Method	
Issued by		Checked by		Approved by		Received by (Receiving Section)	
C. Arevalo QA-IE Staff		G. Magina QA Supervisor		QA Asst. Manager		M. Cepeda Head/ Supervisor	

I. INVESTIGATION / ANALYSIS

DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)		INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)	
System / Training	Why 1: Why 2: Why 3: Why 4: Why 5:	Why 1: Why 2: Why 3: Why 4: Why 5:	
Design / Toolings	Why 1: Why 2: Why 3: Why 4: Why 5:	Why 1: Why 2: Why 3: Why 4: Why 5:	
Process / Material	Why 1: Why 2: Why 3: Why 4: Why 5:	Why 1: Why 2: Why 3: Why 4: Why 5:	

LQA-006-F01 REV.00