KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69

JUNE 23, 2023

INVESTIGATION REPORT

A
Approved By:
R. MIRANDA
/ KPLIMA Operations Gen. Mngr.

5M	M REVIEW DOCUMENT REVIEW					
MAN	No Changes	Affected Document:	Date Reviewed:	Disposition:	PIC:	Target Date:
MACHINE	No Changes	Procedure Manual		With Revision No Revision	K. DIAZ	N/A
MATERIAL	WORN OUT PATTERN SHEET	Work Instruction	230616	With Revision No Revision	K. DIAZ	N/A
METHOD	No Changes	Process Flow	230010	With Revision No Revision	K. DIAZ	N/A
ENVIRONMENT	No Changes	Forms		With Revision ✓ No Revision	K. DIAZ	N/A

I. PROBLEM DESCRIPTION

Fax No. (049) 545-6302

DATE:

1.1. ISSUE: PEEL OFF 1.2. ITEM DESCRIPTION: PART CODE: 516512900 PART NAME: LIGHT 2 MB AMERICA

1.3. BACKGROUND:

PICTURE



DETAILS:

>Inhouse Detection: PEEL OFF

>Lot size: 1993 pcs > Reject Qty: 55 pcs >Rejection Rate: 2.76%

IMMEDIATE ACTION

ACTION ITEMS	Target Date:	Person In-charge
PUT BACKING TAPE ON THE UNCUT PORTION OF TH ITEM.	JUNE 14, 2023	PIC: OPERATOR AND SUBLEADER

III. CAUSE ANALYSIS:

WHY 1:	PEEL OFF DUE TO THE ITEM BECOMING UNCUT WHILE THE MACHINE WAS IN OPERATION.
WHY /	WHEN WE CHECKED THE BLADE, THE BLADE WAS STILL OK, BUT THE PATTERN SHEET (PATCHING AND BACKING TAPE) WAS WORN OUT DUE TO EXCESSIVE USE.
WHY 3:	THE OPERATOR CONTINUED TO USE THE PATTERN SHEET BECAUSE THEY BELIEVED WHAT THEY WERE PERFORMING WAS OK.

IV. ACTION PLAN: V. EVIDENCES:

1 1	RE-EDUCATE THE OPERATOR ON THE CORRECT APPLICATION OF THE MATERIALS OR TOOLS THEY USE.	
	SUBLEADER WILL BE CONCERNED TO REQUEST TOOLING CUSTODIAN FOR REPLACEMENT TOOLS OR EQUIPMENTS	
3	POST OPL ABOUT USING PATTERN SHEET AND BACKING TAPE (APPERANCE)	