KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna					INVESTIGATION REPORT FORM (IRF)					
K	No. 5 Ring Road I Telephone No. (0 Fax No. (049) 545	49) 545-7166 to		Control	Inhouse Detection Customer Claim Control No.: IRF-24-01-0003 Date Issued: 10-Jan-24					
Customer	E	PPI		Attention To N. CEPEDA/ R. ALMARIO						
Item Code	5	164437-002		Departi	nent	KPLIMA- PRODUCTION				
tem Description PAD ASSY				Date of Detection		240109 NS				
Job Order Number 052902					Detected	EPPI IQA				
ILLUSTRATION OF THE PROBLEM				Major Minor						
		NO GOOD ILLU	ISTRATION	Lo	t Quantity (pcs.)	Reject Qu	antity (pcs.)	Reject Percentage		
dini.					40 1			2.50%		
	HOL	A MINISTER		Nature of Defect:						
			MISALIGNED PRINT							
		GOOD ILLUS	STRATION							
	POSITION MA	III III III	jii iii	ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF MISALIGNED PRINT						
_	3	•	7	Actual:						
	воттом	VIEW (SMC	DOTH SURFACE)		MISALIGNED PRINT WAS ENCOUNTERED ON THE ITEM (PLEASE SEE ATTACHED PICTURE)					
N	NO. OF OCCURRENCE DISPOSITION				AREA OF O	CONTENT				
Fir	rst	The state of the s	Hold		Slotter Gluing			Material		
Re	Recurrence Special Acceptance				EQOS	Vertic	cal	Dimension		
No.: Date:			For Rework		Diecut Others:		rs:	Appearance		
			Reject / Disposal		Detaching Process					
	Issued by		Checked by		Approved by			Received by (Receiving Section)		
	√		. ()				Fords	shut		
	J.Tapay		G. Magsino				N. Cepeda/ R. A			
	QA-IE Staff		QA Supervisor		QA Asst. Ma	ager Head/		Supervisor/ Manager		
			I. INVESTIG	ATION /	ANALYSIS					
DII	RECT CAUSE: (Ana	alyze the reaso	on of occurrence, why it happened?)		INDIRECT CAL	JSE: (Analyze the	reason of occur	rence, why it leaked?)		
	ny 1:			Why 1:						
mainim wh	Why 2:									
System / Training	Why 3:									
Syste w	Why 4:									
	Why 5:									
wh	Why 1:									
Silloo W	Why 2:									
Design / Toolings	Why 3:				Why 3:					
Desig	Why 4:				Why 4:					
	hy 5:			Why 5:						
w w	Why 1:				Why 1:					
Mater	'hy 2:			Why 2	Why 2:					
Ss / N	Thy 3:			Why 3	Why 3:					
Process / Material	/hy 4:			Why 4	Why 4:					
	Why 5:				:					

KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

				FINAL CO	NCLUSION					
	OCCURRENCE	ROOTCAUSE			OUTFLOW ROOTCAUSE					
IMMEDIATE ACTIO	N: (Action to be done t	o contain/ temporar	y correct the pr	oblem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)					
A. Sorting Result				Actions to be	done to eliminate recurrence	Who / When				
	Location	Total Stock	NG	Total Good	300d					
RM					System					
WIP										
FG										
B. Orientation										
Date		Time			Design /					
Title	9				Tools					
Attendees										
C. Reworking										
Rework Quantity					Process					
Total Good										
Rework Percentage (Go										
II. QA ROOTCAU	SE VERIFICATION		ut by QA In	-charge)	Date Conducted: PIC:					
	Identified I	Rootcause			Recommendation					
7-20		III. CORRE	ECTIVE ACT	ION VERIFICAT	TION (To be fille	ed out by QA	In-charge)			
	Chec	ked by	Date		nented?		Remarks			
1st Verification of Action				[]Yes	[] No					
2nd Verification of Action				[]Yes	[]No					
3rd Verification of Action		[]Yes	[]No							
Effectiveness of Actio		[]Yes	[] No							
Note: If no same defect deliveries or 3rd verific	cts / problems occu cation of action still	rs for 5 consecu not yet impleme	utive deliveri ented, Investi	es, corrective act gation Report sh	lion is considere all be re-issued	d effective / c to the affecte	losed. If the same problem occu d department to provide new im	rs within 5 consecutive provement action.		
			R. B. B.	IV. CL	OSURE					
Status: Remarks:		Approv		ved by:		Process Owner Acknowledg	gment: (Receiving Section)			
Closed										
Still Open			QA Supervisor		QA Asst. Manager		Line Leader	Department Head		
Re-issue IRF			Date:		Date:		Date:	Date:		