

## Additional Evidence :

Illustration : Replacement of Auto stripper lock of Deicut machine.



Cleaning of Item prior putting of next Batch :

### Uncut Trimmings



### Cleaning / Removal of Trimmings :



### No Occurrence of Dent Mark :

